with. also, slight depression on left side RE may need to be filled after removal of surface debris and/or somehow, outletted.

