Lot 16

DAVID Rt rear

0 - 22" sl firm ps clay / sandy lt maroon
23 - 40" silty clay / SAP clasts
41"+ well weathered SAP

slightly to mod eroded / simple complex topo

.3

Wesley's hole similar

Rae - Lot could accomodate ~~same~~ type of sys but ~~septic~~ boundaries and interior are "cleaned up" and house size / lot known then sys. type is speculative

---

Lot 15

DAVID Lt Rear

0 - 28" Sticky, firm ps clay
29" - 48" silty clay / ~~SAP~~ clasts, very mixed

.3 - .4

Wesley's hole similar

...STEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...NER: Bill Brunker
...DRESS: _____ APPLICANT: _____
...OPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: 12/30/9
...CATION OF SITE: Dick Wyeth Village Lot #15 PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
...ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
...ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
...PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-12"	Brn SCL GR FR						
	12-24"	Red/Brn C mSBK SS		SP SE	F-FR			PS
	24+"	Red/Brn C M-mSBK		SS SP SE	FRW/Common			#3
			M	Micaplakes & Common	SAP Rocks			

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
...ble Space (.1945)		
...n Type(s)		
...TAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____