




LEGEND

- ● Iron found
- ⊗ P.K. nail in a power pole
- ⊙ Calculated point
- △ Concrete monument found (broken)
- ⌖ Phone pole

Copyright © Current Surveying, & Mapping, P.A. January 25, 2006



VICINITY SKETCH



NORTH CAROLINA PROFESSIONAL SEAL L-756 LAND SURVEYOR RICHARD C. CURRENT


I, Richard C. Current, Professional Land Surveyor, (L-756) certify that this map was drawn from an actual field survey performed under my direction and supervision, that said survey conforms to the standards of Land Surveyors of NC and the state laws of NC with the ratio of precision is 1 : [illegible].


Witness my hand and seal this 15 day of Dec 2006.

Richard C. Current, Reg. No. L-756

JOB # 10602

; ON MAP.


N
Bk. 619, Pg. 666
dtd 1-19-78


758.000
Lake
Norman
760.000
S 62°23'00"E
104.76'
762.000
82
54.000
1.03 Acres
By Coordinate Computation
Ref. Bk. 619, Pg. 666
S 21°04'00"E
105.46'
Deck
Dwelling
Pier
Dock

PO FOR:

REVISED : FEBRUARY 15, 2006
CORRECTED ELEVATIONS

RN

TOWNSHIP, IREDELL COUNTY, N.C.
5, 2006 SCALE: 1" = 20'

0 20 40 60

ALE - FEET

SURVEYING & MAPPING, P.A.
HY MOUNTAIN ROAD
D, N.C. 28697
CURRENT, REG. NO. L-756

THIS SURVEY ON THE PART OF THE SURVEYOR
OM OGBURN

AX RECORDS USED TO IDENTIFY
PROPERTY OWNERS. SURVEY
D WITHOUT A TITLE REPORT, WHICH
L ADDITIONAL CONVEYANCES,
-WAY, EASEMENTS, OR OTHER
NS NOT SHOWN.

RVEY IS OVER 2,000.00' FROM ANY
LISHED NC HORIZONTAL GROUND CONTROL

Section 7
14, Pg. 73

al Pool.
Flood Elevation. (Panel # 370313 0200 B dtd 5-15-80)
Power Easement for possible flood.

Lake
Norman

N 56°06'00"E
64.49'

1/2"
Rebar

(Tie Line)
N 89°22'25"E
170.81'

766.000

768.000

770.000

83

Steven Seeberg

Bk. 1458, Pg. 843