DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: 4624 43 0740
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kelly Lane - Pat Jr
ADDRESS: _____ APPLICATION DATE 10/23/03
PROPOSED FACILITY: 4BR House PROPOSED DESIGN FLOW (.1949): 480 DATE EVALUATED: 11/3/03
LOCATION OF SITE: Lot 5 Southpointe PROPERTY SIZE: .69Ac
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	3-4% L CV	0-8	sbk / cl DkBr.	FR SS-SP	PS				PS .3
		9-21	fi sbk / cl RB	VFR SS-SP					
		22-40	sbk / hcl	Fi SS-SP					
		41-49	sbk / c	Fr SS-P.	PS				PS .3
2	CV L 3-4%	0-13	GR / sl	VFR SS-NP					
		14-27	sbk / cl	FR SS-SP					
		28-48	sbk / c Red	FI SS-SP.	PS	PS			PS .3
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	"U"
System Type(s)	PPBPS	?
Site LTAR	.3	?

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Sparks
OTHER(S) PRESENT: Pat Simpson

COMMENTS: >'83 requires 100% Repair w/ no area for it. Will location will require tanks to go over
Phone con w/ Michelle Mercier
Wachovia Rd. side of structure