DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CPE — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 2/97
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: 29A, 17A sawmill Hardee's — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1 New pit (upper side / left side) 29A		0-42	SAB loam						
		42-46	CL/SaCl/we rock						
		0-13	SAB bedrock						
		13-46+	wet rock/we/Sap						
17A 2 Newpit		0-10	gr Brsicl	fr					
		10-26	wSAB RBrm	fr SSSP SSAP	manganese concretions				03
		26-60+	WK SAB RCL	fi fr SSSP SSAP	H2O seeping from rock fractures @ hor change				
			Rumica Holes						
		+60 48"	to depth						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 2-18-87
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 17A Harbour Cy PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut Need BH pits
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed
Poor Landscape Position on West of Site

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS 1943 SOIL DEPTH	OTHER PROFILE FACTORS 1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L C 4-6%	0-6	gr brwsl/scL		Hit Feather @ 36" No mottles	Hemgrain 2-13, 2-14			.75 .85 @ L 36"
		6-15	SAB rbrwcL	fri sp-vs p	sapp	manganese stains			
		15-36	SAB RC	fi-vfi sp-vs p					
		36-48	m-wk SAB	fi sp-ss p-sp					
2	Begin Head Slp L 4-6% 2 (between 0 & 6 Bench)	0-4	gr brwsl/scL fri		(+20) Mgs Mn0	manganese stains few reduced colors			
		4-20	SAB brwR cfi sp-vs, p						
		20-34	SAB RCL	fi					
			Too much rock-bible, Stopped also hit granite						
3	L-C 4-6% Head Slp	0-4	gr brwsl	fr					.75 .85 @ L 42"
		4-16	SAB R brwCL	fi sp SAP					
		16-42	m-wk SAB RCL	fr ss p-sp	Mn inflakes				
		42-48	CL SAP						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___