VISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CBI — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 4/14/97
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: lot 20 Harbour Co — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LPT	0-48							PS, 3
2	edge of Lemmings	0-36	sab gr fr sl	fr-fi sspsspo	(36")				
			reduced colors many f-c						
			mottles beginning @ 16"+		transitional to	mapped at 48"			
			many distinct < 2m 2 mottles		36"+	w/ Tomahawk			
3	L 10-15%	0-4	gr fr sl	fr					PS, 3
		4-32	sab gr sl-fr	fr-fi sspsspo					
		32-48	m sab sl	fr sspsspo					
			few mi spp						
4	L ~15%	0-36	sab fr	fr sspsspo					PS, 3
		36-48	sab fr sl	fr sspsspo					
			numerous manganese throughout						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

0-9 gr fr sl
9-48 SAB RC fr sspsspo
numerous manganese throughout
Seal of Depot with base
~15%

Initial: 145, 75, 75, 40, 335, +335

Repair: 30, 45, 60, 70, 255