SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

APPLICATION DATE: _____

SS: _____ DATE EVALUATED: _____

SED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

TON OF SITE: 361 Farms Rd PROPERTY RECORDED: _____

SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

ATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

F WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-48	RbC MSaSiLm	fri SS, P	- many. One.				.275
	0-23	RL MSaSiLm	fri SP	water seeping in pit				PS looks .25
	0-38	RC MSaSiLm	fri SSSP					.3
	38-53	RCL FSaSiLm	fri SSSP	+ Rocks				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
...ote Space (.1945)		
...n Type(s)		


OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

...ENTS: _____


Linden Falls Ct.
45' R/W
DRIVE
363
0.88 AC.
70x90
360
1.00 AC.
70x90
362
0.73 AC.
60x70
361
0.89 AC.
60x70
SETBACK
63.73'
SETBACK
49.65'
105'
106'
118'
207'
297'
221'
87'
75'
186'
125'
98'
30'
20'
40'
45'
12"RCP
INV=773.
"PVC
NV=777.01
MB
25% grade
80
59+00
58+00
57+00
60+00
1+00