DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-23-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 349 STE Russell Trail PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	#113 TCS	0-13	sl brn sl	fr					PS .3
		13-47	sc/ls RC	fi sp					
2		0-6	gr brn sl	fr					PS .2-.25
		6-33	mfsbk r/brn cl	fr sp					
		33-56	wk/sbk yel cl	fi ss sp SOW	3 slowly permeable horizon				
			common f ending to brn mottles						
			water seeping in pit just above slowly permeable horizon						
3		0-7	brn sl						PS .25
		7-18	mfsbk yel cl	fr ss sp					
		18-39	wk/mas RC	fi sp common f brn mottles					
		39-56	mfsbk c/cl	fi ss sp					
					This pit broke bottle of ~~water~~ ~~soft~~				
4	#114 TCS	0-12	brn sl						PS .25
		12-47	mfsbk RC	common f red/brn mottles fi sp fr sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____