

W 28.86'
E 50.04'
LAKE NORMAN
#6 REBAR FOUND
L1
L2
L3
L4
L5
L6
C.P.
#2 REBAR FOUND 8.36 ON--LINE
760' & 761' CONTOUR FOLLOWS TOP OF BANK AS PER ACTUAL FIELD SURVEY
NEW REPAIR 100'
770.00
50' SETBACK
EXISTING BED
EXISTING
EXISTING
EXISTING
TO BE ABANDONED
100.2
LOT 448
0.65 AC.
NEW TANK
EXISTING TANK
780.00
BASEMENT FFE=778.69'
15' SETBACK
5' SETBACK
58.7
47.7
EX. BASEMENT
NEW HOUSE
FUTURE WALL
71.75'
38.4
ONE BAY ADDITION
65.5'
35' SETBACK
58.9'
790.00
WALL
#4 REBAR FOUND
N 79°19'00" E 167.44 TOT.
S 78°50'00" W 182.96
(BASE BEARING)
N 16°10'00" W
115.97
C1
OHE