DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 1
PROPERTY I.D.#: 2B2A3
PROPERTY RECORDED: Y65
COUNTY: Iredell

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Larry F Hamilton Jr. OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 12/16/93
PROPOSED FACILITY: 3 bedroom SF Dwelling
PROPERTY SIZE: 100' X 200'
LOCATION OF SITE: SR 1102 on Rt just before Schooley Rd — Lot 3, Sedgefield
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring ✓ Pit Cut

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	LS	0-7"	gr - scl	1:1 / vfr wet	—	—	PS	—	.6
		7-48"	w2sbk - c	1:1 / vfi	—	—	PS	—	.3
2									
3									
4									
5									

AVAILABLE SPACE (.1945) PSX SITE CLASSIFICATION (.1948): PSX SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: J Morrison OTHER(S) PRESENT: Larry Hamilton
COMMENTS: Trained Dec 14 pm and all day on Dec 15, '93. Topsoil was saturated & water came into auger holes. Relic mottles were noticed in profile but nothing of chroma 2 or less was noticed.
Lot recorded prior to 1983 – Repair area on site very limited. Owner desires conventional system on site.