DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH


SHEET____OF_____
PROPERTY I.D.#:_____
PROPERTY RECORDED:_____
COUNTY:_____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Brian Hartwick OWNER:__AGENT:__PHONE:_____
ADDRESS:_____APPLICATION DATE: 3/16/95 DATE EVALUATED: 3/16/95
PROPOSED FACILITY: 3 Bd 2 Ba House
PROPERTY SIZE: 184 X 103
LOCATION OF SITE: Corner of Inverness & Regency Blvd (Regency Lake Village)
WATER SUPPLY: On-Site Well ~~✓~~ Comm. Well ✓ Public___Other_____EVAL. METHOD: Auger Boring ✓ Pit___Cut___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	2-4%	0-3	Organic/Clay		—	—	—	—	±0.4
		3-46	1-1 Cly SBK		Non	—	PS	—	
2	2-4%	0-3	Organic/Clay		—	—	—	—	±0.4
		3-48	1-1 Cly SBK		Non	—	PS	—	
3									
4									
5									

AVAILABLE SPACE (.1945) PS SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: ±0.4
EVALUATED BY: KS OTHER(S) PRESENT: Brian Hartwick
COMMENTS: Conv. Gravity as shown w/ PPBPS Repair


Church
House
Thames
Regency