ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Stumpy Creek LLC APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 1-20-98

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: Sec 8 Autumnview Lot 13 PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut Look upslope – maybe a pump system

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (1941): 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS: 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	D- Edge of Drainageway	0-45	SAB R-BRWN C/CL	FR FI SPS EXP					PS .25
			few manganese stains						
			few inches water in pit bottom						
			landscape position problem						
2	Edge of Drainageway	0-38	SAB RBRWN C/CL	FR SP					PS .25
			~8" water in pit bottom						
			landscape position problem						
3	Edge of Drainageway	0-43	SAB R-RBRN C/CL	FR SP SS EXP					PS .25
			few inches water in pit bottom						
			landscape position problem – look upslope						
4		0-42	SAB RC/CL	FR SP-SS SPS EXP					PS .03

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		


OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

PS 0-45 SAB BRN R C/CL FR SP SS SPS EXP PS .03
wet fine brn SL SAP 40"+



"HARBOR VIEW"

TANAGER LANE
LOT #13

DAVIDSON TOWNSHIP **IREDELL COUNTY, N.C.**
JANUARY 09, 1998 **SCALE: 1"= 60'**