DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 11-7-03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 6A SFE Beacon Pt phs 3 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Now 4A

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8	bwL	frssso					
		8-30	sfsbk/mk rc	fi sp sap					
		30-50	(B-C) mksbk cL	frssso	common mk sap				.3
2		0-5	gr bwsd	frssso					
		5-24	mfsbk rc	fr sp sap					
		24-39	mksbk grcL	fr sso	common mk sap				.3
		39-54	massive gy sl sap	frssso					
3		0-4	gr bwsd	frssso					
		4-24	mfsbk rc	fi-frsp sap					
		24-60	massive gy-gybrn LSAp	frssp	common pred sap				.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICATION DATE ___
ADDRESS: ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ DATE EVALUATED: 10-16-23
LOCATION OF SITE: Lot 4 Beacon Pt PROPERTY SIZE: ___
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

#6 0-6 gr brn sl
6-29 scl c fr sbk sap .2
29+ sap / mixed mineral

* U - maybe LAP / shallow on a steep slope - with good construction

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-18	gr brn sl	fr sso p					.25
		18-36 (BR)	wk fsbk	scl fr sso p	common vf sap				
		36-55	massive ybrn L/scl sap	fr sso p	few vf mottles, few vf pores				
2		0-17	gr sdy sl	fr sso p					(4)
		17+	common ch z brn		17"+				
3		0-25	wk fsbk ye scl	fr sso p					.25-.3 @ 2 ft
		25-38	wk m fsbk brn scl	fr sso p					
		38-48	m fsbk ltbrn cL	fr sso p					
			no chz 2 but wet 38+						
4		0-6	gr brn sl	fr sso p					.5
		6-20	m sbk RC	fr sso p sap					
		20-48	wk fsbk ye cl/L	fr sso p common vf sap					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

COMMENTS: ___

#5 ~3% N30% slope
0-15 gr ybrn sl fr sso p
15-21 ybrn scL fr sso p sap
21-39 (BR) scl fr sso p mod w rock
39-47 soil / sap mix - hard sap

Pond's Dump
0-10 sl
10-24 scl
24-43 sl sap vf mod fsbk .25