VISION OF ENVIRONMENTAL HEALTH:
-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9-6-01
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 55 S Templeton Terrace PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed Now 32A

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
55-1	0-5	g-wk sbk brn sl fri fr sssp						
	5-28	sbk RC	fr sp sbk					3
	28-48	wk f sbk/pr yr cl fr sssp common ind snp						
55-2	0-5	gr brn sl	fr sssp					
	5-25	m f sbk RC	fr sp					
	25-48	wk sbk R-yr hard cl	fr sssp few common ind snp					3
		very few w/ manganese on LS 20-48"						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Suitable Space (.1945)		
[illegible]		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____


40' REAR SB
40' FRONT SB
15' SIDE
4' SIDEWALK
190.00'
120.00'
155.61'
140.00'
100.00'
28,451 S.F.
26,600 S.F.
14,400 S.F.
Panel Repair
PPBPS
55
53
52
51
50
STA 12+96.4
STA 0+00