date: 2-3-94 weather:
property description: MILLS FOREST II 5
topography: excavation:

0-2
color:
texture: sl + litter
structure grade: —
size: —
form: gran
consistence: mvfr
boundary: clear

2-4
color:
texture: scl
structure grade: med
size: med
form: gran
consistence: mvfr
boundary: abrupt

4-27
color:
texture: clay
structure grade: wk
size: med (+)
form: sbk
consistence: mvfi
boundary: clear 0,25

27-33
color:
texture: s c
structure grade: wk
size:
form: sbk
consistence: mvfi
boundary: gradual 0,25 - 0,2

Perched wetness on and in this horizon. Previous rainfall ≥ 1 week.

* MUST HAVE: upslope SUBsurface intercept drain, outlet to front

---


33-
color: Mn deposits incr. with depth
texture: sc
structure grade: vwk
size:
form: sbk
consistence: mvfi
boundary: terminated ≥ 0.2

---

color:
texture:
structure grade:
size:
form:
consistence:
boundary:

---

color:
texture:
structure grade:
size:
form:
consistence:
boundary:


WALL

date:
property description: Mills forest — weather: II
topography: — excavation: COMBINE W/ 15

color:
texture:
structure grade:
size:
form:
consistence:
boundary:

UNSUITABLE DUE TO INSUFFICIEN AVAILABLE SPACE AND TOPO.


color:
texture:
structure grade:
size:
form:
consistence:
boundary:

color:
texture:
structure grade:
size:
form:
consistence:
boundary:

color:
texture:
structure grade:
size:
form:
consistence:
boundary:

color:
texture:
structure grade:
size:
form:
consistence:
boundary:

color:
texture:
structure grade:
size:
form:
consistence:
boundary:


IRR. TOPO
IRREGULAR TOPO
DEPRESSIONAL
TOPOGRAPHY
WALL