DIVISION OF ENVIRONMENTAL HEALTH:
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION

208
8 4

OWNER: Perry Jenkins APPLICANT: _____

REVISED: _____ ATTENTION TO: _____ DATE: 2/9/04

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: _____ PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8"	Brw SCL	GR FR					PS
		8"-44"	Rd/Brw C/Cl w/Common Mica Flakes & Few gel/brw mottles starting at 32"	m-w SBK	SS, SP, SE, FR				.3
		44"-48"	CL w/Few to many		SAP Indus				
2		0-6"	Brw SCL	GR FR					PS
		6"-36"	Rd/Brw C/CL	m-w SBK	SS, SP, SE, FR				
		36"	Hit Rock, possibly Floater but couldn't auger through						.3
3		0-8	Brw SCL	GR FR					
		8"-42"	Rd/Brw C/CL w/Common Mica Flakes & Few yellow/brw mottles	m-w SBK	SS, SP, SE, FR				.3
		42+R	CL w/Few to many		SAP Indus				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Total LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____