DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Tom Wynn APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 2-11-02
LOCATION OF SITE: Lot 12 Johnson Creek PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

now part of Revised Lot 9

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	gr-wk sab hor sl	fr ss sp	fr ss sp				.25 / .34
		4-19	wk sab RC	fr ss sp sexy					
		19-49	massive	L/sl ss sp plastic					
2		0-4	wk sab hor sl	fr ss sp					.3
		4-32	wk sab hor-k brn	sc fr ss sp					
		32-48	wk sab brn/k brn	sl fr ss sp					
		48-56	massive wk sab	sl sp fr ss sp					
3		0-12	compacted RC	hill on backhoe cut					.4 / .2.35 / .4
		12-19	organic sand clay	sl cl fr ss sp					
		19-57	massive RY	L/sl ss sp fr ss sp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Tom Wyatt
ADDRESS: ___ APPLICATION DATE ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ DATE EVALUATED: 2-Mar
LOCATION OF SITE: Lot 13 Davidson Creek PROPERTY SIZE: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Not enough suitable space. Now part of Revised Lot 9

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	gr brown scl	fr sso sp					.25
		4-24	sab/AB RC	fi sp					
		24-50	massive LSAP	fi sl cl	fr sso sp				
2		0-5	gr brown scl	fr sso sp					.3 - .25
		5-13	sab/AB c	fi sp					
		13-24	mottled cl	fr sso sp - sp					
				common mi sap					
		24-54	massive cl SAP	fr sso sp mi cl					
3		0-2	wk sab brn scl	fr sso sp					.25 / .3
		2-20	mod sab rc c	fi sp					
		20-29	wk fsab red lam w/ sab	fr sso sp					
		29-57	massive LSAP	fr sso sp					
4		0-5	wk sab brn scl/cl	fr sso sp					.225-.25 / .3
		5-16	mod sab RC	fi sp					
		16-27	wk fsab red	fr sso sp few mi sap					
		27-55	massive Rd LSAP	fr sso sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

COMMENTS: ___