THE WATER
704662-3239 704-528-7355

Att. Shane

Septic tail line encroachment
In existing overhead power line
Right-of-way

August 14, 2015

Jake Nosker
1628 Shearers Rd
Davidson, NC 28036

Ref: Front of lot
PID: 4664485770

It is standard operating procedure that EnergyUnited will allow the tail lines, and underground connecting conduit of a septic system to encroach in an existing, overhead power line. It is understood that the septic tank is not allowed to encroach in the right-of-way strip, and that the tail lines should be as far from the existing structures as possible. Further, it is understood that EnergyUnited will not be liable for damages to the tail lines at any time for any reason even if the damages are the direct result of actions taken by EnergyUnited.

Justin Jones
Staking Technician
EnergyUnited
(704) 896-5407
18019 Old Statesville Road
Cornelius, N.C. 28031