Inspection Report

Health Department Identification Number: #207307 Tax Map: 4626-29-8255

Iredell County Health Department

Name of OSE/PE: Thomas Shuck License Number:

Address: Telephone:

Contractors Name Rowan Septic

Owner's Name: Shea Homes

Owner's Address: 8088 Corporate Center, Charlotte, NC Ste # 200

Location of Installation: Subdivision: Anniston Section: 3 Block: Lot: 113

Other: Site Address: 146 Timberside Drive Davidson, NC

Component	Inspection Results Comments, Materials, Etc. Deficiencies Observed, Date Deficiencies Observed Corrective Action Required	Date Approved
Water Supply Location and Construction		
Building Sewer	N/A	
Septic Tank	Rowan 1000 GAL STD 2-24-15 mid-seam w/mastic Rubber boots "OK"	7-10-15 SH
Inlet-Outlet Structure	Tuff-tite sock filter examined "OK"	7-10-15 SH
Pump and Pump Station TOP SEAM	Rowan 1000 GAL STD 2-14-15 w/cast in place plastic riser, Zoeller N-152 Pump w/ Tri-check valve/union	7-10-15 SH
Conveyance Method	2" SCH-40 PVC force main	7-10-15 SH
Distribution Box or Pressure Manifold	3'x3' conc. box w/ leaky elbow [fixed] 4-lines Balanced OK.	7-10-15 SH
Header, Conveyance, Return, etc. Lines	SCH-40 PVC	7-10-15 SH
Percolation Lines, Drip, Chambers, etc.	23 ea Infiltrator 36" chambers on top line and 25 in other 3 lines with 8 end caps (900 L.F. total) 24"-36" Deep	7-10-15 SH
Absorption Trenches and Dispersal Field	Line 1 (Top) 4' 2¾" 5 shots w/Laser OK Line 2 5' 5" 5 shots w/Laser OK	
(Other Components: treatment unit, etc.)	Line 3 6' 4" 5 shots w/Laser [2" fall @ distal end] OK Line 4 7' 4½" 5 shots w/Laser OK	7-10-15 SH
	* Location + configuration as permitted. - SH	
★	As of 7-10-15, electrical inspection of pump still required.	

Attach observed deficiencies and corrective actions taken on a separate completion statement as necessary.

This form contains personal information subject to disclosure under the Freedom of Information Act.

Revised 12/1/2014