DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Repair

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Joan Burden
ADDRESS: 1567 Lundis Hwy
PROPOSED FACILITY: SFD
PROPOSED DESIGN FLOW (.1949): 360
LOCATION OF SITE: same
APPLICATION DATE _____
DATE EVALUATED: 4/4/08
PROPERTY SIZE: _____
PROPERTY RECORDED: _____

WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 6%	0 – 20	msbkCL	fr SS SP Sexp					.4 (.35) Based on soil in existing tankhole
		20 – 48	Mass SL Sap	vfr nse np					
2	NS 7%	0 – 42	msbk C	fr SS SP					.3
		42 – 48	msbk C	fr SS SP Sexp	YB				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Anthony Cobos Jr
OTHER(S) PRESENT: Owner


4677-07-0150
192
880
17
83
4677-06-1924
485
334
4677-06-0836
4667-96-9804
4667-96-7779
570
537
1573
890
100'
60'
1567
74
55
LANDIS HWY
LANDIS HWY
4667-96-3690
900
171
4667-95-9054
1 inch equals 50 feet