DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 11/14/07
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Bethany Place Lot 1 Albany Rd PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	A	0-24	Massive	F;11	Veins of Chroma 2 common				
		24-45	mSbk Red C	Pr 55 Sp Sexp					
		45-55	mSbk Red C	Pr 55 Sp Sexp	Com rock LOB inc.				
					The Chroma 2's disappear at 45"				
2	B	0-17	Massive	Fill					
		17-47	mSbk C	Pr 55 Sp Sexp	Com rock O Sap				PS .3 see below Fill
		47-58	mSbk CL	vPr 55 Sp Sexp	many Sap				
3	C Repair?	0-14	mSbk Red C	Pr 55 Sp Sexp					
		14-23	mSbk Red C	Pr 55 Sp Sexp	few LOB				PS .3
		23-55	mSbk Red C	Pr 55 Sp Sexp	Com Sap com rock inc.				
4	AB 1	0-19	Fill						
		19-45	mSbk CL	vPr 55 Sp	Com Sap				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Anthony Coker
OTHER(S) PRESENT: David Hinson & owner