DEPARTMENT OF ENVIRONMENT, HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT (2)

SHEET ____ OF ____

PROPERTY I.D.#: ____

DATE: ____

COUNTY Iredell

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: Mayford Wyatt
ADDRESS: ____
OWNER ___ AGENT: ___ PHONE: ____
APPLICATION DATE: ____ DATE EVALUATED 10-2-95
PROPOSED FACILITY: 3 Bedroom DW MH
PROPERTY SIZE ____
LOCATION OF SITE: Lot # 17 Pine Ridge Estates
WATER SUPPLY: On-site Well ___ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS./ SLOPE(%)	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINERALOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
9	6-8%	0-6"	sl	gr	1:1			.1942 Wetness Cond. - PS.
	L	6"-20"	scl	wsbk	1:1	wet soil		.1943 Depth/.1956 Sapr. - NA
		20"-34"	c	Abk/wsbk	1:1 ss,sp	relic matrix		.1944 Restrictive Hori. - NA
		34"-48"	c	Abk	1:1	chroma II mottles		.1948 Profile Class. - PS
								Profile LTAR - .2
10	6-8% L	0-7"	sl	gr	1:1			.1942 Wetness Cond. - PS
		7"-22"	scl	wsbk	1:1	wet soil		.1943 Depth/.1956 Sapr. - NA
		22"-35"	c	Abk/wsbk	1:1 ss,sp	relic matrix		.1944 Restrictive Hori. - NA
		35"-48"	c	Abk	1:1	chroma II mottles		.1948 Profile Class. - PS
								Profile LTAR - .2
18	6-8%	0-7"	fill					.1942 Wetness Cond. - PS
	L	7"-40"	c	wsbk	1:1			.1943 Depth/.1956 Sapr. - NA
		40"-48"	c	Abk	1:1	chroma II mottles		.1944 Restrictive Hori. - NA
								.1948 Profile Class. - PS
								Profile LTAR - .25
12	6-8%	0-6"	sl	gr	1:1			.1942 Wetness Cond. - PS
	L	6"-20"	scl	wsbk	1:1	wet soil		.1943 Depth/.1956 Sapr. - NA
		20"-37"	c	wsbk	1:1			.1944 Restrictive Hori. - NA
		37"-46"	c	Abk	1:1	relic matrix		.1948 Profile Class. - PS.
		46"-48"	c	Abk	1:1	chroma II mottles		Profile LTAR - .25

AVAILABLE SPACE (.1945) U OTHER FACTORS (.1946) ____ SITECLASSIFICATION (.1948) PS.

SYSTEM TYPE ____ LONG-TERM ACCEPTANCE RATE(S) .25.

EVALUATED BY: [signature] OTHER(S) PRESENT: Ernie Punge

COMMENT Unsuitable - Not enough available space for system and 100% Repair Area. Owner does not want letter written, he will combine this lot with another lot.

0002017