Almost impossible to design a workable sewage system on this lot. Tank is 6 ft underground and lines are approximately 15 ft underground near the end. Good soil was found at the bottom of the ditch and it is possible this system will give good service. However this system is approved on construction and will be owners responsibility if it gives trouble.

Mr Johnson approved this layout. In fact this was the only possible layout.