PROPERTY ID #: _____
COUNTY: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dyson/Heritage APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9/10/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #101 Leopard Spgs Ln PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1	3 10	0-7"	Brw SiL GR FR						PS
		7-24"	Rd/Brw L SBK SS, SPSE FR						Rock
		24-45"	Rd/Brw-Brw Cl SS, SPSE FR		Incl SO	Comm	Mica Flakes		.275
		45-48"	Cl/weathered Rock	Common	Mica Flakes			mix	
2	2-3 10	0-6"	Brw SiL FR FR						PS
		6-36"	Rd/Brw L SBK C, SPSE, FF		with Some Rock Frag				.25
		& Mica Flakes							
		37"	Water Coming into hole						
3	5 10	0-6"	Brw SiCL GR FR						PS
		6-25	Rd/Brw Cl mSBK SPSE FF		w/ veins of SAP			weathered	
		25-40"	Rd/Brw Cl mSBK SPSE FF					Rock	.3
		40-48	Brw-Rd/Brw Cl-SCL GR FR						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____