DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dysa / Heritage APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/10/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #93 Lippard Spgs PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	4-Plc	0-7"	Brn SCL GR	FR					PS .3 to 40"
		7"-29"	Rd/Brn C m SBK S-SS, SP SE, FI						
		29-40"	Rd/Brn CL m SBK SS, SP, SE, FR w/ Inclus of weathered Rock & Common Mica Flakes						
		41-	Hit Rock - Could not Auger through						
2	7-8 plc	0-7"	Brn SCL GR	FR					PS .3 to 40"
		7-24"	Rd/Brn C m SBK S-SS, SP SE FI					Many SCL	
		24-45"	Rd/Brn CL m-w SBK SS, SP SE, FR w/ Few to Common Mica Flakes & SAP Inclus.						
		45-48"	Yel/Brn SCL SAP w/ Common Mica Flakes						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____