Septic system 18" below drain field
≈ 13' of fall from tank to field
See revision below (following)

W.E. HOOVER
13-115
195-260

SEPTIC SYSTEM
DO NOT DISTURB

TEMPORARY SEDIMENT BASIN
(SEE DETAIL)

TEMPORARY DIVERSION DITCH

2.3% SLOPE

30" RCP

CB#5 DA=0.35AC
TOP=842.3
INV IN=837.1
INV OUT=836.9

CB#4 DA=1.9 AC
TOP=842.0
INV IN=836.8
INV OUT=836.3

S 42°51'03" W 844
(S61.56')
581.76' TOTAL

CB#3 DA=2.6 AC
TOP=848.4
INV IN=843.7
INV OUT=843.5

CB#2 DA=0.53 AC
TOP=853.3
INV IN=848.0
INV OUT=847.8

FFF 850.5

4 BAYS @ 20'

OFFICE & PARTS

24' RCP

18" RCP

30" RCP

X 8492

S 33°40'11" E
534.51'

SR 2342

TEMPORARY DIVE

W.E. HOOVER
13-115
195-260

0 0 8 8 5