North Carolina
Department of Natural Resources and Community Development
Division of Environmental Management

P. O. Box 27687 - Raleigh, N. C. 27611

WELL ABANDONMENT RECORD

CONTRACTOR _____ REG. NO. _____

1. WELL LOCATION: (Show a sketch of the location on back of form.)
   Nearest Town: TROUTMAN County IREDELL
   WINFORD ROAD - SHINNSVILLE Quadrangle No. _____
   (Road, Community, Subdivision, Lot No.)
2. OWNER: ROBIN + SHARON STEWART
3. ADDRESS: Rt. 1, Bx 464 TROUTMAN
4. TOPOGRAPHY: draw, slope, hilltop, valley, flat
5. USE OF WELL: None DATE: _____
6. TOTAL DEPTH: 100 FT. DIAMETER: 6 in
7. CASING REMOVED:

feet	diameter

8. SEALING MATERIAL:

Neat cement	Sand cement
bags of cement [illegible]	bags of cement 10
gals. of water ___	yds. of sand 10
	gals. of water 10


Other
Type material _____
Amount _____

9. EXPLAIN METHOD OF EMPLACEMENT OF MATERIAL
   Use cement and sand
   to fill the well up. Cut off about 3 feet from
   the top.

I do hereby certify that this well abandonment record is true and exact.

Robin F. Stewart 11-16-87
Signature of Contractor or Agent Date

WELL DIAGRAM: Draw a detailed sketch of the well showing total depth, depth and diameter of screens remaining in the well, gravel interval, intervals of casing perforations, and depths and types of fill materials used.



Submit original to the Division of Environmental Management, one copy to the Driller, and one copy to the Owner.

WELL LOCATION: Draw a location sketch showing the direction and distance of the well to at least two (2) nearby reference points such as roads, intersections and streams. Identify roads with State Highway road identification numbers.

