BROOKVIEW TRAILER PARK 4-24-01

Lot #3:
- Collection sewer pipe leaking under trailer.
- Water leaks also saturating the ground under trailer.
- Water leak in front yard.

Lot #26:
- Effluent not being absorbed by drain lines and overflowing tank. Visible evidence of effluent running down street at certain times.
- Plumber needs to make sure there is no leaks in trailer.

Lot #24:
- No one occupying trailer presently but signs of failing system evident.
- Hole drilled in outlet pipe so sewage will back up in yard when tank and lines are not properly operating.

Lot #20:
- The SEPTIC TANK has collapsed and hole covered up with plywood. TANK NEEDS REPLACING!

Lot #18:
- Occupants are driving on drain lines and yard is becoming muddy. There needs to be no vehicular traffic over drain field area.

Lot #14:
- System appears to be adjacent to creek and <u>may</u> have or is leaking effluent into creek.

Lot #25:
- Lines appear to not be properly absorbing and effluent is backing up into tank and on top of ground.

Lot #20:
- Lines appear to not be properly absorbing and effluent is backing up into tank and on top of ground.

Lot #11:
- Water saturating ground at back of trailer. Does not appear to be effluent but plumber needs to fix it.

Recommended: Place risers on tanks to not allow rain H_2O to stand over them after being pumped.