
Owner of System Phillip Sparks
Repair Completed 11-21-91

Granny's Restaurant



N.C. Hwy 901