DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: C&I APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7-17-96
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 440gpd PROPERTY SIZE: _____
LOCATION OF SITE: Lot 6 Harbour Sect 5 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 8-10%	0-7	gr fr sl	fr					=3
		7-27	sab rcl/c	fi sp l					
		27-60	sab rcl	fi sp l					
			w/ few mi stn						
2	L 8-10%	0-12	gr fr sl	fr					=3
		12-60	sab rcl/a	fi-fr sp l					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 2-30-96
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: SF Easements "F" past Sandel/N PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1 SEE "F"	Pit V 6%	0-3	bk s.l	1:1	NA	>60	PS		0.3+
		3-11	red c						
		11-24	red cl						
		24-41	bl cl w/sap						
		41-55	sap s.l						
2 SEE F	Pit L 6%	0-11	sl bk s.l w/ red bk		M subm mottle gel brow				0.3
		11-24	red bk c						
		24-60	red c						
			53" min of gel. poss soil below						
3 SEE "F"	L 4-6%	0-7	sa b r brn c	fr					.3
		7-14	sa b r w/ c	fr					
		14-36	w/sa b r y c l	fr					
		36-60	sl sap	fr					
4 SEE "F"	L 2-6%	0-3	bk s l						.3
		3-19	red c sapb						
		19-25	red c l w/ sap & bk colors						
		25-60	sl sap few mica w/ thin clay layers						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


J
9 SLIPS
BLOCK 5
5
602
BASEMENT
CRAWL
6
DRIVE
198.33'
S16°02'00"E
N64°14'08"W
270.73'
143' SETBACK
4
3
7
8
N64°02'30"W
66.06'
26.18'
35' SETBACK
82.83'
S10°55'12"E
237.11'
313.32'
74' SETBACK
S63°38'10"W
91.64'
34.26'
44.11'
25.23'
21.45'
79.12'
108.31'
S74°37'08"W
249.95'