VISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7-23-01
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 819 ph 8 The Pt. PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Design @ .25

PROFILE #	(1940) LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	M 12	0-3	wkab brn sl	fri ssp					3
		3-48	sab rc	fri fr sp					
2	(2)	0-8	brn scl	fi ssp	few chr 3 (clearing grinding)				.2 maybe
		8-36	sab rbrn cl	common manganese concretions/coat					
		36-59	sab rc	fi sp					
3	(3) 7-25-01	0-16	sab rbrn c/cb	fi sp	few manganese coatings				.25 / .3
		16-54	wm sab rcb	fri ssp ssp					
				few mn sap					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


755
165
107
BASEMENT
80X100
CRAWL
819 sq. ft.
BASEMENT
80X100
CRAWL
820 sq. ft.
110
260'
39,059
40,621
25'
276'
287'
775
DRIVE
DRIVE
DRIVE
35' FRONT SETBACK
VE
147'
73'
70'
111'
78'
126'