VISION OF ENVIRONMENTAL HEALTH
N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


WNER: ORI APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-27-99
OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: lot 542 Mans Trail PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
'ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-11	massive brn sl						
	11-25	wk sbk ec	LFSP	common y-brn mottles				.2-.25
	25-53	wk sbk gpcl	FR SSSP	few y-brn mottles				=3
#109 TCS	0-7	g brn sl	fr					P5
	7-15	m brn ec	FSP					=3
	15-50	m sbk gpcl	FR SSSP	common med y spp/brn mottles				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
lable Space (.1945)		
m Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____


R=425.00
L=405.53
Tan=219.69
Delta=54°40
DRIVE
DRIVE
DRIVE
35' SETBACK
130'
128'
133'
124'
123'
35' SETBACK
35,604. sq.ft.
31,240. sq.ft.
30,681. sq.ft.
541
542
543
CRAWL
80²
BASEMENT
75X80
256'
235'
262'
130'
127'
127'
LF Panel 320±
Sewer Repair