DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ORL APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-23-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 68 The Peak PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Now Lot 67


Dig another pit 2 pits down hill from 8 Go down 4-21-98 this is 8 with landscape

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1	4-21-98	0-5	gr-slb brwsd fr						PS -3 @ 23"
		5-23	slb rc/cl	fr soapstone					
		23-32	wk sbk rcl	fr soapstone					
		32-49	wk sbk rcl	fr soapstone					
		49-60	Same	micaceous soapstone bedrock					
2		0-21	wk sbk rc	fr sp					PS 13 @ 23"
		21-31	wk sbk gr scl	fr soapstone					
		31-40	Channer Stone Layer						
3		0-7	gr brwsd l	fr					B .3
		7-45	slb rc/cl	fr soapstone					
4	4-21-98	0-8	gr-slb Brwsd	fr					R .3 @ 45"
		8-48	slb rc/cl	fr-fi soapstone					
		48-51	hard soapstone bedrock						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____


AVEN CT.
VINEYARD DRIVE
N59°12'09"
107.
83'
155'
35' SETBACK
157'
197'
169'
S03°09'42"E
140.80'
113'
R=325.00'
L=482.00'
Tan=297.67'
Delta=84°58'26"
67
68
250'
260'
DRIVE
20' PSDE
170'
50' SETBACK
35' SETBACK
116'
103'
L300
Contour
Old Fence
4@100+ per
Pad Installed
w/ pond
repair