

93'
95'
120'
111'
106'
35' SETBACK
153'
249'
214'
211'
115'
205'
247'
70'
RECREATIC
WATERHOUSE
DRIVE
R=320.00'
L=740.98'
Tan=730.22'
Delta=132°40'19"
R=50'
R=36'
110.00'
N71°45'2
60.88'
S14°31"E
92'
55'
39' SETBACK
25' SETBACK
35' SETBACK
60'
268'
30
29
28
CRAWL
CRAWL

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CKT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-24-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 30 The Ponds (Formerly 125) PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1950 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-19	LS GR RC	FR SP					PS .25
		19-46	s-LS gr	FR SSP					
			Common manganese concretions throughout						
			Very few mottles						
2		0-8	SL GR CL	FR					PS .25
		8-43	mot SCL GR RC	FR FI SP					
			Common manganese coatings		Consistence				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____