DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: MJ Fox — APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 1-20-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 13 Lakeview Heights — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut — Too much tree debris, brush from lots 13/14 than Lot 7
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-27	fill/tree debris						(4)
		27-38	SAB rc/cl						
		38-48+	water in pit						
2		0-20	SAB rc/cL	fr sp-ssg					
		20-32	(water in pit						
			(not stopping coinciding LS position)						
3	AH 2-16-99	0-6	wkmb brn sil	fr					PS @25-3
		6-25	SAB RC	fr sp ssg (SL impeded)					
		25-43	wkgr gr sch	fr ss sp ssg					
4		0-5	wkmb brn sil	fr					wet @0-5 mottled
		5-18	SAB rc/cl	fr-fi sp ssp					
		18-48	wkmb gr L	common wk/sp fr ss sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


LOT 16
0.69 AC.
156.11'
120.00'
LOT 5
0.69 AC.
250.0
255.13'
121.15'
LOT 15
0.70 AC.
111' MBL
76.87'
120.00'
145.14'
80.00'
265.85'
118.48'
38.60'
147.37'
LOT 14
0.69 AC.
100.53'
45' PUBLIC R/W
PINE HILL DR.
248.19'
96.35'
10'X70' SIGHT TRIANGLE
R=35.00'
N 49°58'45" E
LOT 13
0.69 AC.
263.40'
EXISTING TREE DEBRIS BURIAL SITE
LOT 12
0.69 AC.
239.29'
35' MBL
EIP
104.25'
117.50'
393.71' TOTAL
N 40°01'15" W