OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
ENVIRONMENTAL HEALTH
WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Lot 18 Village at Pine APPLICANT: Barnes & Dev.
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-31-05
PROPOSED FACILITY: House PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4>2%	0-21	sr/wsbk sl	fr ss/sp	br Red	48L	Fc SN ind 21		PS .3
		21-48	msbk cl	fr ss/sp					
2	L 2 10%	0-20	msbk c	fr s/p	mot red gr 12 mot gr 11	29"	PS		PS .3
		20-29	wsbk scl	fr ss/sp					
		29-48	m cl	fr ss/sp					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS · 3
EVALUATED BY: REP
OTHER(S) PRESENT: _____


LOT 18
found iron rod in creek
N 64°22'45" E
144.91'
found iron rod
Scott R. Nee
Deed book 1163,
Lot 9
R8-A
N 89°41'50" E
161.33'
N 89°41'50" E
179.52'
42.21'
40.00'
L1
L2
L3
L4
L5
L61
L62
branch
PT
16
0.91 acre±
N 00°18'10" W
211.11'
N 48°58'00" E
130.71'
17
0.58 acre±
common open space
L63
C29
28
0.79 acre±
well lot
C19
C18
C17
C20
N 74°54'26" E
90.00'
N 74°54'26" E
133.50'
2" SCH 40 PVC SURVEY
SCALE: 1" = 50'
65' front setback
65'
60'
18
0.69 acre±
BR
C30
GATE VALVE BOX
W 8" WATER
R 20' REPAIR
W 12'
R 10'
L65
C22
C21
N 20°52'58" W
84.75'
N 71°26'32" E
117.05'
S 65°51'21" E
115.71'
S 46°51'46" E
49.84'
L13
L14
L53
REF. PT.
N 25°16'54" W
90.92'
27
0.69 acre±
Approx. Pit Location
house