DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Links Rd PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-58	c-cl sbk	Fr ss sp					PS 0.3
			Ind sap @ 33"						
2		0-5	sl sbk	fr ss sp					PS 0.3
		5-57	c sbk	fr ss sp					
			Ind sap @ 32"						
3		0-60	c-cl sbk	fr ss sp					PS 0.3
			Ind sap @ 36"						
4		0-7	sl gr	fr ss sp					PS 0.3
		7-56	c sbk	fr ss sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____


LPP
nel Repair
System
N 10°27'49" W
245.00'
117.74'
127.26'
474.94'
46'
52'
well
DEVEL
50x50
CRAWL
Yellow 30'
Red 35'
Pink 53'
Blue 37'
Yellow 45'
Red 52'
56'
Pink 67'
Red 74'
Yellow 84'
Blue 95'
Pink 101'
Red 108'
Yellow 108'
Blue 107'
repair
repair
repair
System= 5 x 67'
Repair= 3 x 107'
N 47°20'55" W
L34
C2
C1
C14