DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Hammock #9 PROPERTY RECORDED: SFE #8
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

#5 0-32 C
32-50 LSYP PSO.3

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	SFE #8	0-11	SL	FrSSSP					PS 0.25 0.3
		11-48 C	SBK	FrSSSP					
			Mottled 21	Fr 35					
2	SFE #8	0-36	Y/R C SBK	Fr SP					PS 0.3
		36-52	Y/R L SGP	Fr SCSP					
3		0-4	SL SBK	FrSSSP					PS 0.3
		4-39	C SBK	Fr SSSP					
		39-52	L SGP M	FrSSSP					
4		0-50	C SBK	Fr SP	Jul 98 Chroma 2 @ 37"	0-22"			PS 0.25 TO 32"

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


L14
L15
L17
L16
L32
L33
L30
L31
L84
L83
L85
L87
L89
L90
L91
761' CONTOUR
well
50'
50'
70'x70'
8
9
1.59 acres
10
0 acres
N 71°27'45" E 191.05'
Blue 125' repair
Pink 145'
Yellow 172'
Red 100' repair
Orange 90' repair
Blue 75' repair
Pink 108'
Red 120'
Yellow 105'
Orange 85' repair
Blue 75' repair
Pink 70' repair
35' FRONT SETBACK
20' SEPTIC EASEMENT
456.29'
S 18°32'15" E
324.47'
1" = 50'
50
0
50
100
C20
C21
SEPTIC ESMT.
LOT 8