

167
05
142'
113'
830
820'
820
810
815
815
275'
270'
290'
225'
519'
202'
174'
592'
141'
183'
805
2
43310 SF
3
47490 SF
33
45160 SF
60'
60'
DRIVE
DRIVE
DRIVE
25'
COMMON OPEN SPACE
(50' PUBLIC R/W)
51250

VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CKT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-16-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 3 Wildwood Cove PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

#5 Maybe LPP .125 Odd color coming bw/ parent mat 34" Rock fair com ch 2 sm fragments
(4) B-24" few ch 2 sm fragments fi-fr ssp

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-6	sg brwn sl/l fr						
	6-20	wkAB brwn/brwn scl	fi sssp					.25
	20-43	wkSAB rdbrn/brwn scl	fi sssp scrp					.3
#23 TC	X-28	sl brscl	fi					.25?
	28-47	wkAB red	mix sap fi					
		12"+ WATER IN PIT						
upslope of toe of berm	0-24	brwn scl	fi sssp STP	fi sssp layer comp 24"+? obs 4/15				LPP .125
	24+	cl	many gravel mottles					
	0-15	rdbrn sc/scl	fi sssp					
	15-48	wkAB brwn	few ch 2 com gravel	15"+ (4)				(4)

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
uilable Space (.1945)		
tem Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

...N OF ENVIRONMENTAL HEALTH:
...E WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...ER: CRI APPLICANT: _____
...DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-16-00
...OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
...CATION OF SITE: Lot 28 Cox Wildwood Cove PROPERTY RECORDED: _____
...ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
...ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
...PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-8	gr Mucky	fri					PS 0.3
	8-44	f sdy cl	fri					
	0-36	SNDRCL	fri fr	Pewdr mott at 24"				PS 2.25 @ 18"
	36-42	mottled grl SNDY	fr					
	0-36	SNDRCL	Friable					PS 2.25-3 @ 36"
	36-48	wk subangular blocky	mi bonded					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
...ilable Space (.1945)		
...tem Type(s)		
...TAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____