for ON-SITE WASTEWATER SYSTEM

NER: _____ APPLICANT: _____

DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8-22-01

OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

CATION OF SITE: Lot 44 Templeton Farms PROPERTY RECORDED: _____

ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut


PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
(1)	0-14	wksmb brad sbl	fssscp					.25
	14-41	Mfmb RC	fi sp	few brwn/blk few mn/gray				
(2)	0-9	gr brw sl/sbl	fssscp					.25
	9-15	Mwkmb RC	fi sp scp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____


27,140
415
14,400 S.F.
120.00'
120.00'
80.00'
100.0
40' R
STIAN
3-870
195.99'
97.99'
97.99'
4@70+
LPPPBPs
w/ Similar
Repair
15' SIDE SB
1019.91' TOTAL
S 78°03'00" E
248.68'
222.15'
247.70'
43
32,252 S.F.
44
28,727 S.F.
60x8
LPPPBP
w/ similar
Repair
4@80+ Survival
Very tight
No marks stakes
21+44.36
83.83'
20.71
28,6
OLD
IRON
40
30
60
45'
74.61'
DRIVE
15' SIDE SB
132.82'
N83°23'10"W
R = 45'
51.87'
31.96'
OLD
IRON
DRIVE
70
42
33,527 sq.ft.
211.78'
41
33,279 sq.ft.
211.4
78.18'
97.42'
OLD
IRON
N 54°06'44" E
93.40'
KERR