DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: Joe Smith
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 4/16/08
LOCATION OF SITE: Lynnbrook Lot 8 PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Terrace L 10-15%	0-22	mSbkC	Fr SS SpSap	Com Sap - Many Sap				U
		22-55	MassCLSap	Pr SS Sp					
2	Terrace L 10-15	0-22	WSbkLL	Pr SS SpSap	Many Sap				PS .4
		22-41	MassLSap	vPr SS nP					
		41-55	MassSLSap	vPr vs nP					
3	Terrace L 10-15	0-20	MassSLSap	vPr ns np					PS .4
		20-55	MassLSSap	vPr ns np					
4	Terrace 10-15	0-55	MassLSSap	vPr vs np					.5
5	15-20	0-23	WSbkCL	fr ss nP Sap	Many Sap				.4
		23-55	MassLSap	vPr ns np					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Anthony Coxer
OTHER(S) PRESENT: _____

AC
4/24/08



DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kim Suitt — APPLICATION DATE _____
ADDRESS: Lynnbrook Lot 8 — DATE EVALUATED: 9/24/07
PROPOSED FACILITY: SFD. — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: _____ — PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☑ Pit ☐ Cut — TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	p:t L 8%	0-67	MassLSSap	vfr ns np					PS .4-.45
2	Other side opp pt L 8%	0-67	MassLSSap	vfr ns np	few clay	inclusions			PS .4-.45
3	Auger boring #1	0-9	mSbkCL	fr ss np Sap	many mica few clay	inc.			PS .4-.45
		9-50	MassLSSap	vfr ns np					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): Less. System on Lot
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Anthony Elder
OTHER(S) PRESENT: _____