date: weather:
property description: MILLS FOREST II 19
topography: excavation:

---

(11)
color: —
texture: o/
structure grade: wk
0-8 size: fn
form: gran
consistence: mvfr
boundary: clear

---

color: —
texture: s/
structure grade: wk - mod
8-12 size: fn
form: gran
consistence: mvfr
boundary: abrupt

---

color: —
texture: clay
structure grade: wk
12-26 size: med +
form: sbk
consistence: mfi - mvfi
boundary: gradual LTAR 0.2

---

color:
texture: clay loam
structure grade: mod
26-36 size: med
form: gran & sbk
consistence: mfi - mfr
boundary: gradual LTAR 0.3

---

color: —
texture: s/
structure grade: mod
36- size: fn - med
form: gran
consistence: mfr
boundary: terminated 48"

---


color: —
texture: o/
(12) structure grade: wk
0-6 size: fn
form: gran
consistence: mvfr
boundary: clear

---

color: —
texture: c
structure grade: wk
6-26 size: med + crs
form: sbk
consistence: mvfi - mefi
boundary: clear LTAR 0.1

26-34 Saprolite
wk → massive
crs
sbk.
Terminated

*see notes lot 20. Debris pile at front of lot 19 contains pieces of terra cotta well tile. Over these two lots are foundation remains of three structures (two structures of house/barn size and one of shed size), debris of household items (jars, cooking pots, pottery). Location of old well and privy are unknown



⊗Indicates area of perched wetness, as evidenced by free soil water in auger boring made in October, and by low chroma drainage mottles and hydrophyllic vegetation; The drainage pattern on lot 20 is consistent with the map orientation of the spring downslope as it intersects Millo Creek; indicating a rock fracture pattern under this drainage pasture, up to the knoll. The soil pattern changes most rapidly and dramatically from the west side of lot 20 towards the knoll, and then again southward onto lot 19.