DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 4-16-02
LOCATION OF SITE: Lot 25 Mesa Forest PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9	gr brn sl fr sssp						-3
		9-26	sbk rc	fi sp sspo					
		26-48	mfsbk rd	fr sssp few common in sap					
		48-66	L sap	fr sssp					
2		0-9	gr-wksbk brn sil	fr sssp					.3
		9-25	sbk rc	fr sp sspo					
		25-45	mfsbk rd	fr sssp common in sap					
		45-67	L sap	fr sssp					
3		0-37	sbk rc/d	fr sssp in sap 23"+					.3
		37-68	wksbk L sap	fr sssp					
4		0-38	sbk rc/d	fr sssp few in sap					.3
		38-68	wksbk gr L sap	in sap					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____


EXISTING 60' PUBLIC R/W
R/W
C/L
R/W
S02°03'28"E (245.12'TOTAL)
74.69'
65.52'
50.07'
129.53'
30.04'
30.04
30.04
30.03'
63.89'
(TIE)
129.84'
76.31'
50.07'
(243.80'TOTAL)
S02°03'29"E
10'X70'
SIGHT TRIANGLE
TYP.
35' MBL
35' MBL
LOT 26
LOT 25
0.74 AC.±
+0.10 AC± R/W
=0.84 AC±
0.69 AC.±
+0.09 AC± R/W
=0.78 AC±
S88°59'00"E
230.29'(260.33'TOTAL)
230.25'(260.29'TOTAL)
S88°59'00"E
230.15'(260.18'TOTAL)
S88°59'00"E
15' MBL
25' MBL
25' MBL
35' MBL
35' MBL
15' MBL
N02°06'14"W
N02°06'14"W
140.21'
129.85'
1132.53'
TO EIP (NTS)