

40,592.0 S.F.
N 13° 00' 28" E
301.25'
133.53'
S 82° 24' 46" W
278.3'
125.00'
(23)
34,720.8 S.F.
N 13° 00' 28" E
254.28'
29.96'
CM
(24)
48,671.2 S.F.
R= 278.17'
A= 135.73'
30,937.5 S.F.
N 13° 00' 28"
247.50'
154.96'
(44)
37,242.1 S.F.
N 13° 00' 28" E
233.17'
R= 233.17'
(43)
40,194.4 S.F.
A= 344.77'
R= 278.17'
A= 128.92'
S 14° 56' 55" E
213.77'
R= 278.17'
A= 107.42'
(25)
46,714.4 S.F.
265.00'
S 41° 30' 07" E
309.74'
(26)
62,281.9 S.F.
S 63° 37' 36" E
323.29'
140.00'
155.00'
MARKED
WHITE OAK
EMMA K. BOYD
18-186
18-203
23-118
327-202

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Blaine Sutherland APPLICANT: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 4/20/98
PROPOSED FACILITY: ____ PROPOSED DESIGN FLOW (.1949): ____ PROPERTY SIZE: ____
LOCATION OF SITE: Lot #24 Palamino PK PROPERTY RECORDED: ____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other ____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	5-10%	0-4"	Brn SCL GR	FR					PS .3
		4"-40"	Rd/Brn C/CL	vf-m SBK SS,SP,SE,FI-FR, w/Few to many SAP Weathered Rock Indus					
		40-48"	Rd/Brn C/CL	mixed w/SAPs					
2	5%	0-12"	Brn, SCL GR	FR					PS .25-.3
		12-33"	Rd/Brn, C/CL	w-m SBK SS,SP,SE,FI-FR w/Few SAP Pinches					
		33-	Rd/Brn C/CL	w/Some Chroma 3 mottles					
			Wet — Could be Surface water						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): ____
EVALUATED BY: ____
OTHER(S) PRESENT: ____