
5/17/05

Lot 17 Barringer Estates

For Buyer-Nelson Dellinger

Profile	.1940 Landscp pos. /slope %	Horizon Depth (in.)	Soil Morphology .1941 (a)(1) Texture	(a)(2) Structure	(a)(3) Consistence	Soil Matrix Color	Soil Mottle Color	Other Profile Factors
1	22' to ditch 60' to pavement CC 6-8%	3-0	CL	S F S	FR	2.5YR 3/4	–	.1942 Wetness Condition >52
		0-21	L	m 2/S	VFR	2.5YR 3/4	–	.1943 Soil Depth/ .1956 Saprolite >52
		21-33	FCL	m F S	FR	2.5YR 3/6	–	.1944 Restrictive Horizon >52
		33-37	CL	w F m S	SFi	5YR 6/4	–	1947. Profile Class. P
		37-44	(S)hCL	M m S	mFi	7.5YR 4/6	5YR 4/6 10YR 4/6	Profile LTAR 0.3-.25
		44-52	hCL	W m S	mFi	7.5YR 4/6	10YR 6/4	.1942 Wetness Condition
								.1943 Soil Depth/ .1956 Saprolite
								.1944 Restrictive Horizon
								1947. Profile Class.
								Profile LTAR
2	CC	Similar to Boring #1						.1942 Wetness Condition 37"+
		~37-55	heavy CL	W m S	mFi	7.5YR 4/6 " 5/4		.1943 Soil Depth/ .1956 Saprolite >55
		*						.1944 Restrictive Horizon >55
								1947. Profile Class. P
								Profile LTAR 0.25
3	LCC 55							.1942 Wetness Condition >54
		0-36	light CL	m F m S	FR	2.5YR 4/6		.1943 Soil Depth/ .1956 Saprolite 36/>54
		36-44	L	gR	FR			.1944 Restrictive Horizon >54
		44-54	L SaPl	gR	VFR			1947. Profile Class. P
		Area graded but surface is not compacted						Profile LTAR 0.3
4	LCC 55							.1942 Wetness Condition >53
		Same profile as #1 without 3-0 fill						.1943 Soil Depth/ .1956 Saprolite >53
		+53	hCL	W m S	mFi	7.5YR 4/6	10YR 6/4	.1944 Restrictive Horizon >53
								1947. Profile Class. P
								Profile LTAR 0.3-.25
								.1942 Wetness Condition
								.1943 Soil Depth/ .1956 Saprolite
								.1944 Restrictive Horizon
								1947. Profile Class.
								Profile LTAR
								.1942 Wetness Condition
								.1943 Soil Depth/ .1956 Saprolite
								.1944 Restrictive Horizon
								1947. Profile Class.
								Profile LTAR


Pedestal
Right
briar thicket
Road
trees
Area slightly graded
possible well site
grass
Barringer Dr
House
55'6"
96' to Rd
96' to Rd

Pisgah Ch Rd