ROLLANS *Soil & Environmental Services, PA.*

P.O. Box 832, Mooresville, NC 28115 Phone: (704) 746-5046 Fax: (704) 278-0989

Ashley Rollans, NC Licensed Soil Scientist
Mobile: (704) 746-5046
Email: rollans.ashley@yahoo.com

Attached is an Existing System Inspection of a 3 Bedroom Conventional System with gravity distribution for a Proposed New Residence at 168 Wayside Road (PIN#: 4763039309), Iredell County, North Carolina.

Contents: **Page**

Environmental Health Requirements (Green Sheet)---------- 1

Septic Application---------- 2-3

Zoning Application---------- 4-6

Site Plan---------- 7

Agent Authorization---------- 9


Operations Permit---------- 10

December 30, 2015
Project #: 01-3106
Design By: Rollans Soil & Environmental Services, PA

Scale 1" = 50'

106 ft

OBDULIA TORRES



This Tract: McCoy to Torres

Sarah Anne McCoy
965 1268

Frame bldg.

septic field

gravel

SR 2358

WAYSIDE ROAD

S 7°11'54"E 146.85'

S 16°18'00"W 8.46'

S 11°06'37"W 31.39'

N 16°43'38"E 77.79'

S 85°29'50"E 80.21'

N 04°38'10"E 100.00'

McCoy

0.184 Acre
(8021.0 sq. ft.)

Juan Torres
Obdulia Torres
1844-1012

0.345 Acre
(15038 sq. ft.)

SHED

80.21'

N 85°29'50"W 82.78'

Large Nail (ex)

John H. Fox Etal
998 1395

Samuel E. Hauser, Etal
755 438

John H. Fox
Bobbi Fox
861 321

Deed: 1844-1012

NORTH CAROLINA PROFESSIONAL SEAL L-3246 LAND SURVEYOR JOSEPH W. RAYNER

Recd 2/12/16
ok 2/12/16

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #: 4963039309
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Maribel Torres
ADDRESS: 168 Wayside Rd, Statesville NC 28677
PROPOSED FACILITY: 3BR-Single Family PROPOSED DESIGN FLOW (.1949): _____
LOCATION OF SITE: 168 Wayside Rd, Statesville NC 28677
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut

APPLICATION DATE: 12/30/15
DATE EVALUATED: 1/2016
PROPERTY SIZE: .54AC
PROPERTY RECORDED: _____
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
B 1	4/5%	0-6	BLGr	Fr SS SP		48"	—	—	PS .3
		6-48	RC mmsbK	Fr SS SP					
B 2	4/5%	0-4	BLGr	Fr SS SP		48"	—	—	PS .3 OK EHO 2/12/16
		4-48	RC mmsbK	Fr SSS P	Few SAP + white Mineral				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Conv. Gravity	PPBPS
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: S. Ashley Rollins
OTHER(S) PRESENT: Chad Wagner

COMMENTS: _____