DENR/DEH

ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #: 3774926327
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Donald Johnson
ADDRESS: 403 Gardner Point Dr
PROPOSED FACILITY: SFD
LOCATION OF SITE: Sharon School (L) Stewart Rock (R) Fulbright (R) Gardner
WATER SUPPLY: (Private) • Public • Well • Spring • Other N/A
EVALUATION METHOD: (Auger Boring) • Pit • Cut

APPLICATION DATE 2-28-14
DATE EVALUATED: 3-14-14
PROPERTY SIZE: 1.35 ac
PROPERTY RECORDED: Yes
TYPE OF WASTEWATER: (Sewage) • Industrial Process • Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 8%	0-6	SCL fr	gr SE	PS	PS	26"-48"		Drip .15
		6-12	C fi	SBK SE					
		12-26	BC fi/f	WABK SE					
		26-48	Scpl fr	mass N/A					
2	L 13%	0-6	SCL fr	gr SE	PS	PS	N/A	N/A	PS .3
		6-20	C fi	SBK SE					
		20-48	BC fi/f	WABK SE					
3	L 15%	0-6	SCL fr	gr SE	PS	PS	N/A	N/A	PS .3
		6-20	C fi	SBK SE					
		20-48	BC fi/f	WABK SE					
4	L 13%	0-6	SCL fr	gr SE	PS	PS	N/A	N/A	PS .3
		6-21	C fi	SBK SE					
		21-48	BC fi/f	WABK SE					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	25%	Drip
Site LTAR	.3	.15

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: H Snow
OTHER(S) PRESENT:

COMMENTS: