PARTMENT OF ENVIRONMENT,
ALTH, & NATURAL RESOURCES
VISION OF ENVIRONMENTAL HEALTH

SHEET____OF_____
PROPERTY I.D.#:_____
PROPERTY RECORDED:_____
COUNTY:_____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

PLICANT:_____OWNER:__AGENT:__ PHONE:_____
DDRESS:_____APPLICATION DATE:_____DATE EVALUATED: 08/09/97
_____PROPOSED FACILITY:_____
_____PROPERTY SIZE:_____
OCATION OF SITE: Lot 11 SECTION 8 RIVERWALK Subd.
ATER SUPPLY: On-Site Well✓ Comm. Well___Public___Other_____EVAL. METHOD: Auger Boring✓ Pit___Cut___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	S 9%	0-18	C	Fi SE			IV / III		U
		18-22	C+S	FR SE					
		22"	Sap						
2	L 7%	0-10	CL	FR SE			III / II		.350
		10-48	C	Fi SE					
3	R 3%	0-5	cl	fr SE					.35
		5-35	c	fi SE					
		35-48	C+SAP	Fi SE					
4	R 4%	0-9	cl	fr					shallow trench .3
		9-24	c	Fi					
		24-33	c+SAP	Fi					
		33"	saprolite						
5									

AILABLE SPACE (.1945)_____SITE CLASSIFICATION (.1948):_____SITE LONG-TERM ACCEPTANCE RATE:_____
ALUATED BY: EJF RAB JGD OTHER(S) PRESENT:_____
OMMENTS: Vegetation Too Thick To Effectively Eval. Lot. Clearing -