DEPARTMENT OF ENVIRONMENTAL HEALTH
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: ____
COUNTY: Randall

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Doug McNeil APPLICANT: ____
ADDRESS: ____ APPLICATION DATE: 3 8 2000 DATE EVALUATED: April 4, 2000
PROPOSED FACILITY: 4Bdrm House PROPOSED DESIGN FLOW (.1949): 480 PROPERTY SIZE: 1 Ac
LOCATION OF SITE: Lot 4 Riverbend on left off Fulbright from Stevens Rd PROPERTY RECORDED: ____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other off shallow well
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFIL CLASS & LTAF |
|---|---|---|---|---|---|---|---|---|---|
| 1 | H.L 5-8% | 0-8 | SL | | | | | | PS .25 |
| | | 8-36 | SAPM C | FR SS SP | | | | | |
| | | 36-52 | SAS C+/Rock | FR | | | | | |
| 2 | LF 5-6% | 0-6 | SL | | | | | | PS .25 |
| | | 6-30 | SASM C | FR SS SP | | | | | |
| | | 30-49 | SAS C+Rock | FR | | | | | |
| 3 | L 5-8% | 0-10 | SL | | | | | | PS .3 |
| | | 10-38 | SAS C | FR SS SP | | | | | |
| | | 38-52 | SAS C+Rock | FR | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | Conv. | Conv. |
| Site LTAR | .3 | .25 |

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: JC Potter
OTHER(S) PRESENT: ____