DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Roger Manuel
ADDRESS: _____
APPLICATION DATE: 22 Aug. 06
DATE EVALUATED: 8 Sept-06
PROPOSED FACILITY: 3bk house
PROPOSED DESIGN FLOW (.1949): 360 gpd
PROPERTY SIZE: 0.687 ac.
LOCATION OF SITE: Stewart Rock Rd. Robbins River Hills 61
PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 5%	0-30	sbk / c	fr / ss sp?	NA	>48	NA	NA	PS 0.3
		30-48	ws sbk / c	fr / ss sp?					
2	L 5%	0-36	sbk / c	fr / ss sp?	NA	>48	NA	NA	PS 0.3
		36-48+	ws sbk / s	fr / ss sp?					
3	L 6%	0-40	sbk / sc	fr / ss sp?	NA	>48	NA	NA	PS 0.3
		40-48+	ws sbk / sc sp	fr / ss sp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III	III
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: TCH
OTHER(S) PRESENT: _____

COMMENTS: _____